



$1/32$	=	.03125
$1/16$	=	.0625
$3/32$	=	.09375
$1/8$	=	.125
$5/32$	=	.15625
$3/16$	=	.1875
$7/32$	=	.21875
$1/4$	=	.25
$9/32$	=	.28125
$5/16$	=	.3125
$11/32$	=	.34375
$3/8$	=	.375
$13/32$	=	.40625
$7/16$	=	.4375
$15/32$	=	.46875
$1/2$	=	.5
$17/32$	=	.53125
$9/16$	=	.5625
$19/32$	=	.59375
$5/8$	=	.625
$21/32$	=	.65625
$11/16$	=	.6875
$23/32$	=	.71875
$3/4$	=	.75
$25/32$	=	.78125
$13/16$	=	.8125
$27/32$	=	.84375
$7/8$	=	.875
$29/32$	=	.90625
$15/16$	=	.9375
$31/32$	=	.96875